



## Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests		Status	Cost	Declined	Approved	
1. REPLACE THE ENGINE OIL AND DRAIN PLUG GASKET			\$44.88		X	
2. MPI			\$0.00		X	
3. ROTATE TIRES, INSPECT FOR WEAR AND ADJUST PRESSURE \$37.88 + GST/SS			\$37.88		X	
Subtotal			\$82.76		\$82.76	
Inspection & Additional Recommendations		Insp	Status	Cost	Declined	Approved
Mount and balance 4 new tires (All tire tread depth measures 4/32 - 5/32": Will need tires soon)		x	Caution	\$912.88	X	See AI-23
Perform brake system fluid exchange (Brake fluid flush due based on time)		x	Caution	\$125.25	X	See AI-63
Replace steering rack assembly (Found power steering fluid low)		x	Caution	\$1,489.35	X	See AI-141
Subtotal				\$2,527.48	\$2,527.48	
PREFORM ALIGNMENT WITH REPLACEMENT OF RACK				\$119.95	X	
Subtotal				\$119.95	\$119.95	
Totals, Taxes and Fees				Cost	Declined	Approved
Estimate Subtotal				\$2,730.19	\$2,647.43	\$82.76
Tire Levy				\$0.00		\$0.00
Shop Fee				\$48.00		\$0.00
Tax				\$136.51		\$4.14
Estimate Total				\$2,914.70		\$86.90
For "See AI-" items <span style="background-color: black; color: black;">XXXX</span> see the "Additional Info						

*This Honda Odyssey was bought in November 2008.*



## Additional Information

Below is information we feel would help you better understand some of the reasons for taking preventive maintenance steps -- steps that help to ensure the reliability and safety of your vehicle for you and your family.

\*\* The following section may contain instructions for servicing various components of your vehicle. These are an overview of the process that will be performed by a skilled technician in our shop. They are not intended to be a guide for a "do-it-yourself" operation.



## Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. REPLACE THE ENGINE OIL AND DRAIN PLUG GASKET
- ✓ 2. MPI
- ✓ 3. ROTATE TIRES, INSPECT FOR WEAR AND ADJUST PRESSURE \$37.88 + GST/SS



## Package Results

Quick lube inspection

Cautioned Task	Observation	Recommendation
Inspect power steering fluid level, condition and check for leaks	Found power steering fluid low	Replace steering rack assembly
Measure left front tire tread depth	5/32": Inspect tire next service	
Measure right front tire tread depth	5/32": Inspect tire next service	
Measure right rear tire tread depth	5/32": Inspect tire next service	
Measure left rear tire tread depth	5/32": Inspect tire next service	
Inspect overall tire wear and condition	All tire tread depth measures 4/32 - 5/32": Will need tires soon	Mount and balance 4 new tires
Inspect brake fluid level, condition and check for leaks	Brake fluid flush due based on time	Perform brake system fluid exchange

### Passed Tasks

- |   |   |  |
|---|---|--|
| ✓ Inspect automatic transmission fluid level, condition and check for leaks | ✓ Inspect hazard light operation  | ✓ Inspect brake light operation                            |
| ✓ Inspect back-up light operation   | ✓ Inspect taillight, turn signal, side marker, and license plate lights | ✓ Inspect headlight and fog light operation                |
| ✓ Inspect windshield wiper and washer operation                             | ✓ Inspect all vehicle wiper blades                                      | ✓ Check engine oil level and condition and check for leaks |
| ✓ Inspect engine coolant level, condition and check for leaks               | ✓ Inspect accessory drive belts   | ✓ Inspect all hoses and clamps                             |
| ✓ Check and adjust front tire pressure                                      | ✓ Inspect axles, driveshaft(s) U-joints and CV joints/boots             | ✓ Check and adjust rear tire pressure                      |
| ✓ Inspect suspension components   |   |  |

Additional Observations	Recommendation
ALIGNMENT WITH REPLACE OF RACK	PERFORM ALIGNMENT WITH REPLACEMENT OF RACK